Approved For Release 2001/07/27 : CIA-RDP81B00878R000800050071-6 CMCC 151X5.1334

Copy 3 of 3

6 January 1959

11 1 8 8 41 44 8

25X1A 25X1A Dear

The purpose of this letter is to advise you of a temporary delay in the delivery schedule of the ALR-14 equipments. After a delay of approximately seven weeks, deliveries are now being made at the scheduled rate. A revised delivery schedule is enclosed with this letter.

Reason for Delay: During tests of completed systems, an intermittent malfunction occurred. The symptoms were subtle and escaped detection for some time. The solution was not straight forward but was eventually traced to a defective switch in the control panel. To solve the problem, nearly the complete quantity of control panels had to be completely disassembled and rewired.

Sincerely.

STATOTHR

Encl. 1 ALR-14 Test & Delivery Schedule

Copy: Contracting Officer

Approved For Release 2001/07/27: CIA-RDP81B00878R000800050071-6

25X1A

SYSTEM III M-2 (ALR-TEST AND DELIVERY SCHEDULE

1958 - 1959

	NO N	DEC.	JAN.		FEB.	MAR.	APR.	MAY
SYSTEM TEST .	104	105 10	6 107 108	110 011 601	112 113	1 711 911 511 117 1	106 107 108 109 110 111 112 113 114 115 116 117 118 119 120 121 123 124	123 124
AL INSPECTION & PACKING	104	105	106 107	108 109 110	112	113 114 115 116 1	117 118 119 120 121	122 123 124
DELIVERY TO CUSTOMER		$\begin{array}{c} \text{20} & \mathbf{A}_{\sqrt{\lambda}} _{\mathbf{d}} \\ \text{20} & \mathbf{A}_{\sqrt{\lambda}} _{\sqrt{\theta}} \end{array}$	\$\ldot \ldot	801 801 V123	211 III 011 801 A A A A A A A A A A A A A A A A A A A	113 114 115 116 11	7 118 119 120 A	121 122 123 124 \textbf{A} \text